

LINCOLN COUNTY

SITE ID:	Priceless Gas	Cleanup Site ID: 5945	FS ID: 36318758
Alternate Name(s): MERIT TRUCK STOP INC, MERIT TRUCK STOP, INC, PRICE LESS GAS, Priceless Gas			
LOCATION:	WRIA: 53	Lat/Long: 47.654 -118.156	View Vicinity Map
Address:	1108 MORGAN ST DAVENPORT 99122	Township Range Section 25N 37E 21	Legislative District: 13 Congressional District: 5
STATUS:	Construction Complete-Performance Monitoring	Rank:	View Site Web Page View Site Documents
	Responsible Unit: Eastern	Site Manager: Boatsman, Michael	Statute: MTCA
	Is Brownfield?	Has Environmental Covenant? Yes	Is PSI Site?
	NFA Received?	NFA Date:	NFA Reason:

ASSOCIATED CLEANUP UNIT(s)

culD	Cleanup Unit Name	Unit Type	Process Type	Unit Status	Size (Acres)	ERTS ID
6403	PRICE-LESS GAS	Upland	Ecology-supervised or conducted	Construction Complete - Performance Monitoring		E501021

SITE ACTIVITIES:

Applies to:	Related ID (Unit-LUST-VCP)	Activity Display Name	Status	Start Date	End Date	Legal Mechanism	Performed By	Project Manager
CleanupSite		Site Discovery/Release Report Received			11/13/1998			Charloe, Debbie
CleanupSite		Initial Investigation / Federal Preliminary Assessment	Completed	11/13/1998	11/13/1998		Ecology	Charloe, Debbie
CleanupSite		Early Notice Letter(s)			1/22/1999			Charloe, Debbie
CleanupSite MilestoneType		Ecology Emergency Action	Completed	11/23/1998	11/14/1998		Ecology	Charloe, Debbie
CleanupSite MilestoneType		Ecology Remedial Investigation and/or Feasibility Study	Completed	6/24/1999	4/9/2001	Enforcement Order	PLP	Boatsman, Michael
CleanupSite MilestoneType		Ecology Cleanup Action Plan	Completed	5/1/2001	6/30/2003		Ecology	Boatsman, Michael
CleanupSite MilestoneType		Ecology Cleanup Action-Engineering Design	Completed	6/2/2003	4/30/2004		Ecology w/ Contractor	Boatsman, Michael
CleanupSite MilestoneType		Ecology Cleanup Construction	Completed	7/1/2004	3/31/2005		Ecology	Boatsman, Michael
CleanupSite MilestoneType		Ecology Post-Cleanup O & M	In Process	4/1/2005		Enforcement Order	Ecology	Boatsman, Michael
LUST	5071	LUST - Notification		11/16/1998	11/16/1998			Charloe, Debbie
LUST	5071	LUST - Site Characterization Report						
LUST	5071	LUST - Report Received		4/12/1999	1/13/1999			
LUST	5071	LUST - Report Received		3/1/2011	3/9/2011			

LUST	5071	LUST - Report Received		6/29/2011	6/29/2011				
LUST	5071	LUST - Report Received		1/12/2006	1/16/2006				
LUST	5071	LUST - Report Received		4/29/2011	5/4/2011				
LUST	5071	LUST - Report Received		6/27/2007	6/27/2007				
LUST	5071	LUST - Report Received		8/28/2013	8/30/2013				
LUST	5071	LUST - Report Received		6/22/2012	6/27/2012				
LUST	5071	LUST - Report Received		8/26/2005	9/6/2005				
LUST	5071	LUST - Report Received		1/10/2014	1/13/2014				
LUST	5071	LUST - Report Received		4/2/2013	4/4/2013				
LUST	5071	LUST - Report Received		4/4/2012	4/6/2012				
LUST	5071	LUST - Report Received		8/20/2006	8/21/2006				
LUST	5071	LUST - Report Received		5/24/2013	6/4/2013				
LUST	5071	LUST - Report Received		1/12/2007	1/16/2007				

AFFECTED MEDIA & CONTAMINANTS:

Media:

Contaminant:	Ground Water	Surface Water	Soil	Sediment	Air	Bedrock
Benzene	C					
Petroleum Products-Unspecified					C	
Petroleum-Gasoline	C					
Petroleum-Other	C		C			

Key:

B - Below Cleanup Level
C - Confirmed Above Cleanup Level
S - Suspected

R - Remediated
RA - Remediated-Above
RB - Remediated-Below

CleanupSiteDetails2014